

Wei Zhou 25 Wallas AVE st ives NSW 2075

Ref: PVD1820718 - Small Unit Designer

Inspection Report 2 Shirlow ST Marrickville NSW 2204

The small generation unit (solar panel system) at the above address was inspected under the requirements of the *Renewable Energy (Electricity) Act 2000* and *Renewable Energy (Electricity) Regulations 2001* administered by the Clean Energy Regulator. A copy of the final inspection report is attached.

As required by the Regulations, if the draft report contained a likely adverse finding, the inspector has allowed a reasonable opportunity to receive comment from the Agent and/or installer. The inspector has taken into account these comments provided when finalising this report.

The Clean Energy Regulator will be providing a copy of the inspector's final report to the following parties:

- 1) the owner of the solar panel system and the occupier of the premises;
- 2) the person who created the certificates for the solar panel system;
- 3) the designer and installer of the solar panel system;
- 4) the Clean Energy Council; and
- 5) NSW Fair Trading, Energy & Utilities Unit, Home Building Services

If you wish to make any comments on the final report, please provide them directly to the relevant party.

The Clean Energy Regulator is responsible for taking appropriate compliance and enforcement action if certificates are found to be improperly created. The administration or enforcement of safety standards for electrical work and for matters relating to the design and construction of buildings and structures (including solar panel systems) is the responsibility of state and territory regulators.

The relevant State or Territory regulator is NSW Fair Trading, Energy & Utilities Unit, Home Building Services www.fairtrading.nsw.gov.au 13 32 20. If you would like further information about the Clean Energy Regulator's inspections scheme, please visit the website on http://ret.cleanenergyregulator.gov.au, or contact the Renewable Energy Target (RET) Inspections Manager 02 6159 3990 or email retinspections@cleanenergyregulator.gov.au.

Regards

Chris Branson General Manager

Renewables & Carbon Farming Division

2 Sep 2014

Inspection Report Dated 2 Sep 2014 Report Summary

Solar panel system detail	
Installation Address	2 Shirlow ST Marrickville NSW 2204
Installation Date	28 Aug 2013
CER Identification Code	PVD1820718
Owner Name	Stuart Mueller

Inspection summary		
Date of Inspection	23 Jul 2014	
Consent Provider	Stuart Mueller	
Inspection Company	MEA	
Inspection Company Contact Details	Email inspections@masterelectricians.com.au or Phone 1300 889 198	
Inspector	Aaron Ozdirik (002CER-025)	

Overall assessment (found at the time of the inspection)	
Industry Best Practice	

Recommendation

Industry Best Practice - The system complies with all relevant standards and requirements for installation. No safety, performance or documentation issues have been identified. The workmanship and equipment layout are of a high standard. No rectification work is required.

Comments on the draft inspection report

Any comments provided on the draft inspection report by: a) the person who created the certificates; b) the installer; or c) designer of the systems, have been included in this final inspection report.



Inspection report

Details of solar panel system	
Installation Address	2 Shirlow ST Marrickville NSW 2204
CER Identification Code	PVD1820718
Owner Name	Stuart Mueller
Installation Date	28 Aug 2013
Date of Inspection	23 Jul 2014
Consent Provider	Stuart Mueller
Inspection Company	MEA
Inspection Company Contact Details	Email inspections@masterelectricians.com.au or Phone 1300 889 198
Inspector	Aaron Ozdirik (002CER-025)
Installer Name (Recorded in REC Registry)	ming jiang (A9299891)
Installer Contact Details (Recorded in REC Registry)	61 The Trongate ST South Granville NSW 2142
Designer Name (Recorded in REC Registry)	Wei Zhou (A5189725)
Designer Contact Details (Recorded in REC Registry)	25 Wallas AVE st ives NSW 2075
Agent Name (Registered Person recorded in REC Registry)	Natural Energy Group Pty Ltd
Agent Contact Details (Recorded in REC Registry)	david_portelli@yahoo.com
Date draft report provided to Installer	01 Aug 2014
Date draft report provided to Designer	#Error
Date draft report provided to Agent	01 Aug 2014
Comment provided by Installer	No
Comment provided by Designer	No
Comment provided by Agent	No

Item(s) requiring attention/improvement

Nil



General Comments

Installer General Comments
Nil
Designer General Comments
Nil
Agent General Comments
Nil

Clause-Specific Comments

Nil